


PART II

(TO BE FILLED BY THE SDE OF PWD B&R DEPTT.)


SCHOOL SAFETY CERTIFICATE

- a) I have visited the above mentioned school on 17 Feb 2022 and have visually inspected it from all angle of safety and I find it fit for normal use as school building.
- b) In case any additional/alteration or expansion and modification to this building is to be carried out, the same be carried out under the supervision of a technically qualified engineer and this certificate may again be obtained after the completion from the undersigned.
- c) In case the building is affected by flood or if there is settlement of walls / foundations or safing of roofs etc. immediately inspection of the under signed be arranged to check the stability and safety of the building.
- d) This building can be safely occupied for normal use upto 31/3/2022
(Indicate year upto which it can be used)


Sub-Divisional Engineer
Constn. Sub Division No.2
PWD B&R Br., Ludhiana.
Sub Divisional Engineer

Endst. No. 258-68 Dated: 21/02/2022

Copy forwarded to the Principal of G. H. Khalsa College of Education, Gurusar, LDM for further necessary disposal. No additional / alteration or expansion and modification to this building is to be carried out without permission of the undersigned.


Sub-Divisional Engineer
Constn. Sub Division No.2
PWD B&R Br., Ludhiana.